

	A	B	C	D	E	F	G
1	Location: (ped or terminal address or description)	Actions: Be descriptive i.e. test results, corrective action taken, etc...	CMS Required Y/N	CMS Tracking Number	Job Required Y/N	Job Number	Date complete
2	MM 20.3 Hwy 33	Place new cable along Hwy 34 near - WYDOT Permit Submitted ETR 4-30			Y	E.721174	2/8/2015
3	MM 20.3 Hwy 34	Place new cable through washed out area. Place pedestals ETC 2-27	Y	15010760			2/18/2015
4	Hwy 34 MM 21.5	resplice ped, complete	n				2/24/2015
5	169 Sybille Rd	repaired ped, complete	n				2/24/2015
6	Hwy 34 MM 21.36	check splice- re-stencil ped, complete	n				2/24/2015
7	Hwy 34 MM 21.43	secured ped lid, complete	n				2/24/2015
8	Hwy 34 MM 31.8	Check branch splice Mule creek rd and hwy 34 complete	n				2/26/2015
9	Hwy 34 MM 32.5	50 pr SS, check splice. Complete	n				2/26/2015
10	Hwy 34 MM 32.6	50pr SS, check splice. Complete	n				2/26/2015
11	Hwy 34 MM 32.8	Ped 138.336 BS, Removed mouse and nest repaired ped complete	n				2/26/2015
12	Hwy 34 MM 33	Xbox 137.2, removed abandoned drop complete	n				2/26/2015
13	Hwy 34 MM 33	50 pr SS, Tightened ped bolts complete	n				2/26/2015
14	Hwy 34 MM 33.8	plastic 12" ped, straightened ped complete	n				2/26/2015
15	Hwy 34 MM 34.9	Xbox 3490, Check splice, complete	n				2/26/2015
16	Hwy 34 MM 34	inspect splice OK	n				3/5/2015
17	Hwy 34 MM 34.2	inspect splice OK	n				3/5/2015
18	Hwy 34 MM 34.3	inspect splice, secured lid OK	n				3/5/2015
19	Hwy 34 MM 35.1	M125.3 inspected loop OK	n				3/5/2015
20	Hwy 34 MM 35.6	M 12.5 inspected loop OK	n				3/5/2015

	A	B	C	D	E	F	G
21	Hwy 34 MM 35.8	ped 3950 repaired ped	n				3/5/2015
22	Hwy 34 MM 35.9	Inspected splice OK. Will tighten guy when thawed .	n				3/5/2015
23	Hwy 34 MM 40	ped 4016 Secured Lid	n				3/5/2015
24	Hwy 34 MM 38.3	Inspect splice, repaired ped, OK	n				3/6/2015
25	Hwy 34 MM 39.2	Inspect splice, secured lid, OK	n				3/6/2015
26	Hwy 34 MM 40.1	Inspect splice, repaired ped, OK	n				3/6/2015
27	Hwy 34 MM 42.3	inspect splice OK	n				3/9/2015
28	Hwy 34 MM 42.8 ped 4294	inspect splice OK	n				3/9/2015
29	Hwy 34 MM 43.2	inspect splice, Ok	n				3/9/2015
30	Hwy 34 MM 43.6	inspect splice, replace cattle protection Ok	n				3/9/2015
31	Hwy 34 MM 43.8 ped 4384	repaired ped, complete	n				3/9/2015
32	Hwy 34 MM 44.6	Set Post, replaced cattle protection OK	n				3/9/2015
33	Hwy 34 MM 44.9	inspect splice, tightened lid, OK	n				3/9/2015
34	Hwy 34 MM 45	inspect splice, OK	n				3/9/2015
35	Hwy 34 MM 45.1	inspect splice, OK	n				3/9/2015
36	Hwy 34 MM 44.5	inspect splice, OK	n				3/10/2015
37	Hwy 34 MM 44.6	re- bonded cable OK	n				3/10/2015
38	Hwy 34 MM 45.3	inspect splice, OK	n				3/10/2015
39	Hwy 34 MM 45.5	respliced ped, OK	n				3/10/2015
40	Hwy 34 MM 42.6	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036855			3/17/2015
41	Hwy 34 MM 46.7	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036859			3/17/2015
42	Hwy 34 MM 47.3	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036862			3/17/2015
43	Hwy 34 MM 48.3	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036863			3/17/2015

	A	B	C	D	E	F	G
44	Hwy 34 MM 48.8	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036864			3/17/2015
45	Hwy 34 MM 49.0	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036865			3/17/2015
46	Hwy 34 MM 42.3	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15010765			3/18/2015
47	Hwy 34 MM 43.2	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036856			3/18/2015
48	Hwy 34 MM 43.6	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036857			3/18/2015
49	Hwy 34 MM 44.6	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036858			3/18/2015
50	Hwy 34 MM 47.1	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036860			3/18/2015
51	Hwy 34 MM 47.8	Place cattle protection around pedestal, rehab pedestal and cable. ETC 4-15	y	15036861			3/18/2015
52	Hwy 34 MM 20.5	Check peds, need cattle protection. ETC 4-30	y	15033662			3/18/2015
53	Hwy 34 MM 37.4	Plastic ped needs cattle protection	y	15054940			3/19/2015
54	Hwy 34 MM 41	Plastic ped needs cattle protection	y	15054941			3/19/2015
55	Hwy 34 MM 41.4	removed mice, repaired ped , needs cattle protection	y	15054942			3/19/2015
56	Hwy 34 S. of MM 44.6	800' S of Hwy exposed cable needs buried approximately 75'	y	15054943			3/19/2015
57	Hwy 34 MM 23.1	inspected splice- Ok checked aerial creek crossing- ok	n				3/23/2015
58	Hwy 34 MM 45.6	replaced ped, respliced cable- ok	n				3/23/2015
59	HWY 34 MM 46.1	respliced 100pr 19 ga, removed mods repaired ped	n				3/24/2015
60	Tunnel Rd	Bury exposed cable, several locations along road. 500 ft ETC 4-30	y	15010764			3/30/2015
61	Brookside Rd Repeater 1	Place new H-fixture. Rehang equipment. Replace foot bridge. ETC 4-15	y	15010766			3/31/2015
62	Hwy 34 MM 46.6	Place new H-fixture. Rehang equipment. ETC 4-30	y	15036866			3/31/2015
63	Hwy 34 MM 47.8	Place new H-fixture. Rehang equipment. ETC 4-30	y	15036867			3/31/2015
64	MM 3692 Hwy 34	Place new H fixture. Repair existing fencing ETC 2-27	Y	15010759			4/8/2015
65	HWY 34 MM 46.4	inspected splice, found ok	n				4/30/2015
66	HWY 34 MM 46.1	inspected splice, found ok	n				4/30/2015
67	HWY 34 MM 46.6	inspected splice, found ok	n				4/30/2015

	A	B	C	D	E	F	G
68	HWY 34 MM 46.8	inspected splice, found ok	n				4/30/2015
69	HWY 34 MM 46.9	inspected splice, found ok	n				4/30/2015
70	HWY 34 MM 46.91	inspected splice, found ok	n				4/30/2015
71	HWY 34 MM 47.1	respliced 19ga 100pr, ok	n				4/30/2015
72	Tunnel Rd	Cable maintenance, ped maintenance	n				5/1/2015
73	Tunnel Rd	inspected cable route, 6 pedestals, 2 repaired.	n				5/5/2015
74	Palmer Canyon Rd	Cable maintenance, ped maintenance. 3 pedestals 1 repaired	n				5/8/2015
75	Harris Park Rd	Bury exposed cable, several locations along road. 300 ft. ETC 4-30	Y	15010763			5/20/2015
76	Tunnel Rd area	Cable maintenance, ped maintenance. 6 peds 2 repaired	n				6/2/2015
77	Wheatland Reservoir	Cable placement 3000 ft 6 pr 19g cable, rehab,	n				6/9/2015
78	Wheatland Reservoir	cable rehab, ped resplice	n				6/9/2015
79	Wheatland Reservoir	cable placement rehab	n				6/9/2015
80	Wheatland Reservoir	Cable placement, 3000ft 6 pr 19g cable, rehab	n				6/10/2015
81	Wheatland Reservoir	cable placement rehab	n				6/10/2015
82	Wheatland Reservoir	Cable placement, 3000ft 6 pr 19g cable, rehab	n				6/11/2015
83	Wheatland Reservoir	cable rehab,	n				6/16/2015
84	Wheatland Reservoir	contract work to dig in small section to pedestal	y	Pending			
85	Solstice Dr. at reservoir	cable, fence and ped maintenance. 1 pedestal repaired	n				6/24/2015
86	Fish Creek rd, , Harris Park rd	place new anchor and down guys, tightened	y	15134618			6/27/2015
87	Solstice Dr. at reservoir	cable, fence and ped maintenance. 1 pedestal repaired	n				6/29/2015
88	Harris Park Rd	Aerial work, reattach and tighten down guys	n				6/30/2015
89	58 Mule Creek Rd	Replace 420 feet of 6 pair cable. Roy Mathis residence. ETC 4-30	y	15010761 - Pending			